


Wrapid Tape™

HCA, HCO, HCC


Primer-less, Crosslinked, Corrosion Protection Tape.

Product Description




Canusa Wrapid Tape™ is supplied in 15 m length bulk rolls, in several widths to suit the project diameter.

Storage & Safety Guidelines




To ensure maximum performance, store Canusa products in a dry, ventilated area. Keep products sealed in original cartons and avoid exposure to direct sunlight, rain, snow, dust or other adverse environmental elements. Avoid prolonged storage at temperatures above 35°C (95°F) or below -20°C (-4°F). Product installation should be done in accordance with local health and safety regulations.

Equipment List




Propane tank, hose, torch & regulator
 Appropriate tools for surface abrasion
 Knife, roller, rags & approved solvent cleanser
 Digital thermometer with suitable probe
 Standard safety equipment; gloves, goggles, hard hat, etc.


Flame Intensity & Torch Size




Surface Preparation



Ensure that the PE coating edges are beveled to 30°. Clean exposed steel and adjacent pipe coating with a solvent cleanser to remove the presence of oil, grease, and other contaminants.




Ensure that the pipe is dry before cleaning. Prepare the steel joint area to a minimum of S13 /SP3. Lightly abrade the pipe coating adjacent to the weld area to a distance of 50mm (2") beyond each end of the area to be taped.




Wipe clean or air blast the steel and pipe coating to remove foreign contaminants.

Pre-Heat




Pre-Heat the joint area to the minimum required temperature **HCA: 60°C (140°F)** **HCO: 75°C (165°F)** **HCC: 60°C (140°F)**. Using a temperature measuring device, ensure that the correct temperature is reached on the steel and at least 50mm (2") on each side of the tape.

Tape Installation




Starting at least 50mm (2") onto the pipe coating, begin wrapping the tape around the joint, ensuring a minimum 50% spiral overlap. Ensure that the powdered tape side is placed onto the pipe. Remove any plastic release liners as the product is wrapped.


For Sales & Information, Call Toll Free: (888) 532-7937



Continue wrapping the pipe ensuring a minimum 50% overlap.




Warm the tape end and press down firmly. A hold-down tape can be used to secure the tape end.



Using a torch, begin at the edge of the tape and heat circumferentially around the joint, working back to the other edge.


Inspection



Visually inspect the taped joint for the following:

- Tape is in full contact with the joint and extends 50mm (2") onto the pipe coating.
- Adhesive flows at the tape edges.
- No cracks or holes in the tape.

Backfilling Guidelines



Tape Usage Guide

Nominal Pipe Diameter	Recommended Tape Width		Length of Tape Required		The table at left shows the typical usage for 3D and 5D bends, assuming a line coating cutback of 150 mm (6") and a 50 mm (2") overlap onto the pipe coating.
			3D Bend	5D Bend	
	DN inches	mm inches	m feet	m feet	
25	1	50 2	2.8 9.3	2.8 9.3	<p>For other sizes, the following formula can be used: Length of tape = $\pi \times \text{pipe diameter} \times L/W$ where L=length of area to be covered, and W= 1/2 of tape width (for 50% overlap)</p>
40	1.5	50 2	4.0 13.2	4.6 15	
50	2	50 2	5.2 17	6.2 20.3	
80	3	50 2	8.5 28	10.6 34.7	
100	4	50 2	12.3 40	14.8 48.6	
125	5	75 3	11.1 36.4	13.6 44.6	
150	6	75 3	14.3 46.9	18.3 60	
200	8	100 4	16.3 53.4	20.8 68.2	
250	10	100 4	23.1 75.8	30.6 100.4	
300	12	100 4	30.4 99.8	40.9 134.2	
>300	>12	150 6	see formula at right		

Material Usage Table