Figure 1 OVP2 Outline Drawing




Figure 2 Banding the OVP2 to a Test Station or Pipe Wall




Figure 3 Pin Brazed Stud Connection to a Pipe Wall




Figure 4 Flange Mount Using Tapped Holes or Pin Brazed Studs




Figure 5 Flange Mount Using Tapped Holes or Pin Brazed Studs




Figure 6 Flange Mount Using Existing Flange Bolts

